

Work Order ID 84933

84933

Page 1

May-29-12 3:00:18 PM

Item ID: D209-669-043

Accept

N900040100

Setup Start ***NS1***

Revision ID: \

Item Name: Replacement Skidtube

Stop ***NS2***

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: MLJ

Date: 12/05/29 Tooling:

Date:

Run Start ***NR1***

QC:

Date: SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D2906	Rev B

100 0.00

100

DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy D209-669 bluefile & type labels per PPP D205-669-043 Chg 002

003 per EEN 12591 W

NA. J

110 0.00

110

Skidtubes

Skidtubes

Memo

0.00

Skidtubes

- Inspect mat'l D2500-1-190 for damage

-Drill pilot holes using drill jig DT8149, DT8711-2 & DT8711-3 (Do not use cutting fluid)

-Open holes to 0.500" as per Dwg D2906 without cutting fluid

-Deburr and blow out all chips from

-Acid etch and Alodine tube per QSI 005 4.1

> CF 12-6-18

SAD 12.00.18
7/6 12.1

NOTE: Date & initial all
H-I-Form Quality Assurance Approval

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

Entries

Work Order ID 84933

May-29-12 3:00:18 PM

84933

Page 2

Item ID: D209-669-043

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Replacement Skidtube

Stop

NS2

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120

QC3- Inspect Part Finish

0.00

120

QC

Memo

0.00

Quality Control

12-6-18

130

Skidtubes

0.00

130

Skidtubes

Memo

0.00

Skidtubes

-Bond web in place per QSI 015. Allow 12 Hrs. cure time before cutting

Pick:

Qty Part Number Description Batch

A/R Sikaflex-291

Sikaflex expire date: *13-4-12*

Start Time: *15:45*

Date: *12-6-18*

Fin Time: *3:00*

Date: *12-07-04*

pick:

Qty

P/N

description

B/N

1

D2926-3

Web

384949

CFB 12-6-18

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR # _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 84933

May-29-12 3:00:18 PM

84933

Page 3

Item ID: D209-669-043

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Replacement Skidtube

Stop

NS2

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
140		0.00							
140	BENDING MACHINE - CROSSTUBES								
CNC Bend 1	Memo	0.00							
CNC Delta 100 Bender	1-Bend as per program COB43FWD & COBRAFT on CNC Bender and Folio FT								
	2-Cut tubes as per Dwg. D2906								
150		0.00							
150	Skidtubes								
Skidtubes	Memo	0.00							
Skidtubes	-Deburr ends and remove marks from bending								
	- Insert D4202-1 spacer, swage as per QSI002 and trim/ grind flush per QSI002 and dwg. Hold x-bolt with DT9701 Use tube expander 1/2 x17G to start expansion and finish with 1/2 x 18G to achieve dwg dimention.								
160		0.00							
160	QC5- Inspect part completeness to step on W/O								
QC	Memo	0.00							
Quality Control									

7 DE / 12/06/19

BE 12/06/19

DE 12/07/09

BE 12/07/09

1 0 BE 12/07/09

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 84933

May-29-12 3:00:18 PM

84933

Page 4

Item ID: D209-669-043

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Replacement Skidtube

Stop ***NS2***

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start ***NR1***

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

170

0.00

170

Large Fab

Skidtubes

Memo

0.00

Skidtubes

-Drill holes for wearplates using DT8217 Open holes to 19/64", adjust stopper
not to hit web. Debur

-Drill pilot holes for aft & fwd cap using DT8215 open holes to #6" Debur

-Drill pilot holes for Tow ring using DT8091-3 , open to .640" and Debur

190

0.00

190

QC5- Inspect part completeness to step on W/O

QC

Memo

0.00

Quality Control

8/17/07/05

40

12-7-4

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 84933

May-29-12 3:00:18 PM

84933

Page 5

Item ID: D209-669-043

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Item Name: Replacement Skidtube

Stop ***NS2***

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start ***NR1***
Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
200	Pressure Wash per QSI005 4.3	0.00							
200									
HandFinish	Memo	0.00							
Hand Finishing									
210	White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum	0.00							
210									
Powdercoat	Memo	0.00							
Powder Coating	START TIME: 11:15 OVEN TEMPERATURE: 320°F FINISH TIME: 11:45								
220	QC3- Inspect Part Finish	0.00							
220									
QC	Memo	0.00							
Quality Control									

1 0 12-8-5

1X 0 12/07/05

1 0 12/07/05

M121841

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 84933

May-29-12 3:00:18 PM

84933

Page 6

Item ID: D209-669-043

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Replacement Skidtube

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

230

0.00

230

HandFinishing

HandFinish

Memo

0.00

Hand Finishing

1-Install inserts & wearplates as per Dwg. D2906. Use a drop of Sikaflex on insert holes before installing wearplates

A/R Sikaflex-291 12/4/09Sikaflex expire date: 13/07

2-Coat D2594-3 O' rings with Petroleum Jelly and install on D2594-1 plugs as per Dwg D2906

3-Inspect for foreign object per QSI 024

4-Install D2855 Fwd & Aft Cap as per Dwg D2906 and seal Fwd & Aft Cap with Sikaflex. Clean excess adhesive

A/R Sikaflex-291 12/4/09Sikaflex expire date: 13/07

5-Wing Walk as per Dwg D2906 and QSI 005 4.4

Batch: 12/6/131 2 3 12/07/06

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 84933

May-29-12 3:00:18 PM

84933

Page 7

Item ID: D209-669-043

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Item Name: Replacement Skidtube

Stop ***NS2***

Start Date: 29/05/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 16/07/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
240	QC5- Inspect part completeness to step on W/O	0.00							
240									
QC	Memo	0.00							
Quality Control	Inspect Aft Cap, Fwd Step and Wing Walk of work to Current Step Inspect for Foreign objects per QSI 024								
250		0.00							
250	Packaging								
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPPD209-669-043								
	Location: _____								
	PPP Rev: <u>PPP 84909</u>								
260	QC21- Final Inspection - Work Order Release	0.00							
260									
QC	Memo	0.00							
Quality Control									

12/7/12

12/7/18

MF

12-07-18

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

May-29-12 3:00:21 PM

Page 1

Work Order ID: 84933

84933

Parent Item: D209-669-043

D209-669-043

Parent Item Name: Replacement Skidtube

Start Date: 29/05/2012

Required Date: 16/07/2012

Start Qty: 1.00

Required Qty: 1.00

Comments: new IPP 08.02.13 LL, verified by: DD
IPP Rev:B remove DT # in seq140 DD 10.03.10 Verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4202-1 *D4202-1* Spacer		Manufactured	No				Each	81.0000		19			
									**	DC 12/07/04			
				<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>							
				LG	5								
				77727	5								
				LG002	76								
				78806	6								
				79810	70								
D2500-1-190 *D2500-1-190* Ext'n -1' Beam Tube 4"		Manufactured	No			110	Each	91.0000	1	1			
									**	CF 12-6-18			
				<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>							
				HALL	91								
				74777	14								
				80061	77								
D2926-3 *D2926-3* Web		Manufactured	No			110	Each	0.0000	1	1			
									**	CF 12-6-18			
D2855 *D2855* Cap		Manufactured	No			230	Each	21.0000	2	2			
									**	2 12/07/05			
				<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>							
				FP002	21								
				65519	2								
				73347	16								
				75074	3								

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

May-29-12 3:00:21 PM

Page 2

Work Order ID: 84933

84933

Parent Item: D209-669-043

D209-669-043

Parent Item Name: Replacement Skidtube

Start Date: 29/05/2012

Required Date: 16/07/2012

Start Qty: 1.00

Required Qty: 1.00

AN3-5A Purchased No

AN3-5A

Bolt

230 Each 1,090.000 4 4

**

4

(28)

12/07/05

Location

Loc Qty

Loc Code

ST350

1090

115371

46

117423

124

118626 ✓

31

119355

200

120187

500

121185

189

AN960JD10L ~~✗~~ NAS1149D0332J ✓ Purchased No

*AN960JD10I *

Washer

ALS7-1032-130

Purchased No

230 Each 0.0000 4 4

**

44

(28)

12/07/05

121011

230 Each 2,136.000 44 44

**

44

(28)

12/07/05

AI S7-1032-130

Insert

Location

Loc Qty

Loc Code

ST280

51

117717

27

118966

22

119775

2

ST282

2085

119530

73

120181

12

121444

2000

121288 ✓

May-29-12 3:00:21 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

May-29-12 3:00:21 PM

Page 3

Work Order ID: 84933

84933

Parent Item: D209-669-043

D209-669-043

Parent Item Name: Replacement Skidtube

Start Date: 29/05/2012

Required Date: 16/07/2012

Start Qty: 1.00

Required Qty: 1.00

AN3C4A

Purchased

No

230

Each

1,458.000

44

44

AN3C4A

BOLT

**

44

(28)

12/07/05

Location

Loc Qty

Loc Code

ST350

1458

120187

57

120521

28

120769

38

121203 ✓

1000

121556

335

AN960C10L

~~13~~

NAS1149C0332

Purchased

No

230

Each

0.0000

44

44

*AN960C10I *

122063

**

44

(28)

12/07/05

washer

D2594-3

Manufactured

No

230

Each

2,418.000

14

14

D2594-3

O-Ring, 205 Skidtube

**

14

(28)

12/07/05

Location

Loc Qty

Loc Code

FP001

2418

65518

41

79496

984

79573

50

79755 ✓

1343

May-29-12 3:00:21 PM

Shop Packet Print

Page 3

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

May-29-12 3:00:21 PM

Page 4

Work Order ID: 84933

84933

Parent Item: D209-669-043

D209-669-043

Parent Item Name: Replacement Skidtube

Start Date: 29/05/2012

Required Date: 16/07/2012

Start Qty: 1.00

Required Qty: 1.00

D2594-1

Manufactured No

230

Each

311.0000

14

14

D2594-1

Plug, 205 Skidtube

**

14

(2P)

12/07/05

Location

Loc Qty

Loc Code

FP001

98

73401

30

74442

18

79495

50

FP-A

213

73401

0

78590 ✓

213

D3564-9

Manufactured No

230

Each

22.0000

1

1

D3564-9

Wearshoe

**

1

(2P)

12/07/05

Location

Loc Qty

Loc Code

FG

84870 ✓

4

76950

4

FP001

18

67590

4

69943

1

82255

13

D3564-11

Manufactured No

230

Each

8.0000

1

1

D3564-11

Wearshoe

**

1

(2P)

12/07/05

Location

Loc Qty

Loc Code

FG

84871 ✓

4

77056

4

FP001

4

80341

4

May-29-12 3:00:21 PM

Shop Packet Print

Page 4

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

May-29-12 3:00:21 PM

Page 5

Work Order ID: 84933

84933

Parent Item: D209-669-043

D209-669-043

Parent Item Name: Replacement Skidtube

Start Date: 29/05/2012

Required Date: 16/07/2012

Start Qty: 1.00

Required Qty: 1.00

D3564-5 Manufactured No 230 Each 13.0000 1 1
D3564-5
Wearshoe ** 1 (DP) 12/07/05

Location	Loc Qty	Loc Code
FG	2	
34806	2	
FP001	11	
77609	3	
82254 ✓	8	

D3566-1 Manufactured No 230 Each 31.0000 2 2
D3566-1
Gasket ** 2 (DP) 12/07/05

Location	Loc Qty	Loc Code
FP	-22	
81619	10	
FP002	53	
68924	2	
80919	3	
83898 ✓	16	

D3566-5 Manufactured No 230 Each 21.0000 1 1
D3566-5
Gasket ** 1 (DP) 12/05/05

Location	Loc Qty	Loc Code
FP	12	
82275 ✓	12	
FP002	9	
80374	3	
82274	6	

May-29-12 3:00:21 PM

Shop Packet Print

Page 5

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



QTY	QTY	Part Number	Description
-041	-043		
X		D2906-041	SKIDTUBE ASSEMBLY
	X	D2906-043	SKIDTUBE ASSEMBLY
1	1	D2500-1-190	EXTRUSION
22	19	D2579	CROSS BOLT SPACER
12	14	D2594-1	PLUG
12	14	D2594-3	O-RING
2	2	D2855	AFT CAP
1		D2926-1	WEB
	1	D2926-3	WEB
1	1	D3564-9	WEARSHOE (REPLACES D2577-1)
1	1	D3564-11	WEARSHOE (REPLACES D2577-3)
1	1	D3564-5	WEARSHOE (REPLACES D2577-5)
1		D3564-15	WEARSHOE
2	2	D3566-1	GASKET
1	1	D3566-5	GASKET
1		D3566-15	GASKET
50	44	ALS7-1032-130 or AKS7-1032-130 or AKS4-1032-130 or ALS4-1032-130	INSERT
50	44	AN3C4A	BOLT
4	4	AN3-5A	BOLT
50	44	AN960C10L	WASHER
4	4	AN960JD10L	WASHER

GENERAL NOTES:

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 2) LENGTH OF D2500-1 EXTRUSION BEFORE BENDING = 190 INCHES.
- 3) INSERT D2926-1/3 WEB TO LOCATION SHOWN OFF AFT END OF SKIDTUBE AND BOND WEB INTO OUTER TUBE WITH NON-STRUCTURAL SIKAFLEX-241/291 ADHESIVE PER DART QSI 015 BEFORE BENDING. ENSURE HOLES LINE-UP.
- 4) BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.
- 5) BEND AS A SMOOTH RADIUS STARTING WITH A MAXIMUM CENTERLINE RADIUS OF 60 AND ENDING WITH A MINIMUM RADIUS OF 30. A MAXIMUM REDUCTION OF 0.200 IN DIAMETER IS ALLOWABLE IN THE BENT PORTION OF THE TUBE.
- 6) USE DART DRILL TEMPLATE DT2906-041T1 (D2906-041) OR DT2906-043T1 (D2906-043) TO LOCATE AND DRILL Ø0.297 HOLES FOR WEARSHOE INSERTS. INSTALL ALS7-1032-130 PER SECTION C-C AFTER FINISH. INSTALL AN3C4A BOLTS AND AN960C10L WASHERS WITH SIKAFLEX-241/291.
- 7) WELDING TO BE DONE PER DART QSI 004.
- 8) FINISH:
ACID ETCH, ALODINE PER DART QSI 005 4.1 PRIOR TO INSERTING D2926-1/3 WEB. POWDER COAT ASSEMBLY WHITE (REF 4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT AS INDICATED PER DART QSI 005 4.4
- 9) INSERT D2594-1 PLUG CW D2594-3 O-RING IN HOLES MARKED 'P' (BOTH SIDES OF TUBE) AFTER FINISH (12 PLACES).
- 10) ALL DIMENSIONS ARE IN INCHES.

RELEASED

07.04.04

B	UPDATE DRAWING FORMAT; RE-ORGANIZE; ADD STAINLESS STEEL WEARPLATES AND GASKETS CHANGE WEARPLATE HARDWARE TO SS; PG 1: ADD NOTE 10; PG 2 C7: REMOVE AFT Ø0.640 HOLE FROM -041; PG 3 C3: CORRECTED -043 CAP P/N; PG 3 D7: 38 PLACES WAS 44 PLACES;	CB	07.08.21
A	NEW ISSUE	CP	04.06.22
REV.	DESCRIPTION	BY	DATE
DESIGN			
DRAWN			
CHECKED			
MFG. APPR.			
APPROVED			
DE APPR.			
DATE	07.08.21		

DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWING NO.	REV. B
D2906	SHEET 1 OF 3
TITLE	SCALE
AH-1 (209) SKIDTUBE ASSEMBLY	NTS
COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

Dart Aerospace Ltd


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



D2906-1 DRILLING DETAIL




D2906-041 BENDING AND CUTTING DETAIL




D2906-041 ASSEMBLY DETAIL

84933




**DETAIL A
SCALE 1:4**



**DETAIL B
SCALE 1:4**

RELEASED

07.09.04



**SECTION C-C
SCALE 1:4**

AFTER DRILLING AND BENDING ASSEMBLY
PERFORM THE FOLLOWING FOR Ø0.508 HOLES ONLY:
1. CHAMFER HOLE 0.050 X 45°
2. INSERT D2579 SPACER (22 PLACES)
3. WELD INTO PLACE AND GRIND FLUSH
4. C.BORE D2579 SPACER TO Ø0.437 X 1.00 DEEP

DESIGN	9	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	CB	DRAWING NO.	REV. B
CHECKED	PH	D2906	SHEET 2 OF 3
MFG. APPR.	21	TITLE	SCALE
APPROVED	JP	AH-1 (209) SKIDTUBE ASSEMBLY	1:24
DE APPR.		COPYRIGHT © 2004 BY DART AEROSPACE LTD	
DATE	07.08.21	THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR CORRED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



D2906-3 DRILLING DETAIL





D2906-043 BENDING AND CUTTING DETAIL



D2906-043 ASSEMBLY DETAIL


84933



DETAIL B
SCALE 1:4

RELEASED

07.09.04



SECTION C-C
SCALE 1:4

- AFTER DRILLING AND BENDING ASSEMBLY PERFORM THE FOLLOWING FOR 0.508 HOLES ONLY:
1. CHAMFER HOLE 0.050 X 45°
 2. INSERT D2579 SPACER (22 PLACES)
 3. WELD INTO PLACE AND GRIND FLUSH
 4. C'BORE D2579 SPACER TO 0.437 X 1.00 DEEP

DESIGN	47	DART AEROSPACE LTD	
DRAWN	C.B.	HAWKESBURY, ONTARIO, CANADA	
CHECKED	PH	DRAWING NO.	REV. B
MFG. APPR.	PH	D2906	SHEET 3 OF 3
APPROVED	PH	TITLE	SCALE
DE APPR.	PH	AH-1 (209) SKIDTUBE ASSEMBLY	1:24
DATE	07.08.21	COPYRIGHT © 2004 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries